


## **BUSSOLE E RIDUZIONI PER PUNTE INTEGRALI**

*Bushing and chucks for jobber drills*

*Aufnahmen für spiralbohrer*

*Portabrocas*




Ø D	
2	B35/2
2.5	B35/25
3	B35/3
3.2	B35/32
3.5	B35/35
4	B35/4
5	B35/5

## **MANDRINI PER PUNTE COMPONENTI**


*Drill Holder*

*Spannfutter*

*Portabrocas*



Ø D	
8	M40/8
10	M40/10



Ø D	
8	M46/8
10	M46/10