



**FRESE ELICOIDALI POSITIVE HW INTEGRALE**
*HW Solid carbide spiral router bit*
*VHM Vollhartmetallfräser*
*HW Fresas helicoidales integral*

**Z = 1**

Ø D	L	I	POS.
3	50	12	FE1.3-50/12.P
4	50	12	FE1.4-50/12.P
5	50	17	FE1.5-50/17.P
6	60	17	FE1.6-60/17.P
6	60	27	FE1.6-60/27.P
8	80	22	FE1.8-80/22.P
8	80	32	FE1.8/80/32.P
10	80	32	FE1.10-80/32.P
10	100	42	FE1.10-100/42.P
12	80	32	FE1.12-80/32.P
12	100	42	FE1.12-100/42.P
12	100	52	FE1.12-100/52.P

**Z = 2**


Ø D	L	I	POS.
3	50	12	FE2.3-50/12.P
4	50	12	FE2.4-50/12.P
5	50	17	FE2.5-50/17.P
6	60	17	FE2.6-60/17.P
6	60	27	FE2.6-60/27.P
8	80	22	FE2.8-80/22.P
8	80	32	FE2.8-80/32.P
10	80	32	FE2.10-80/32.P
10	100	42	FE2.10-100/42.P
12	80	32	FE2.12-80/32.P
12	100	42	FE2.12-100/42.P
12	100	52	FE2.12-100/52.P
14	100	42	FE2.14-100/42.P
14	100	52	FE2.14-100/52.P
16	100	42	FE2.16-100/42.P
16	100	52	FE2.16-100/52.P
16	120	72	FE2.16-120/72.P
18	100	52	FE2.18-100/52.P
18	120	72	FE2.18-120/72.P
18	150	102	FE2.18-150/102.P
20	100	52	FE2.20-100/52.P
20	120	72	FE2.20-120/72.P
20	150	102	FE2.20-150/102.P


## FRESE ELICOIDALI POSITIVE HW INTEGRALE

HW Solid carbide spiral router bit

VHM Vollhartmetallfräser


HW Fresas helicoidales integral

**Z = 3**



Ø D	L	I	POS.
8	80	22	FE3.8-80/22.P
8	80	32	FE3.8-80/32.P
10	80	32	FE3.10-80/22.P
10	100	42	FE3.10-100/42.P
12	80	32	FE3.12-80/32.P
12	100	42	FE3.12-100/42.P
12	100	52	FE3.12-100/52.P
14	100	42	FE3.14-100/42.P
14	100	52	FE3.14-100/52.P
16	100	42	FE3.16-100/42.P
16	100	52	FE3.16-100/52.P
16	120	72	FE3.16-120/72.P
18	100	52	FE3.18-100/52.P
18	120	72	FE3.18-120/72.P
18	150	102	FE3.18-150/102.P
20	100	52	FE3.20-100/52.P
20	120	72	FE3.20-120/72.P
20	150	102	FE3.20-150/102.P
25	150	102	FE3.25-150/102.P

**Z = 3**



Ø D	L	I	POS.
8	80	22	FE3R.8-80/22.P
8	80	32	FE3R.8-80/32.P
10	80	32	FE3R.10-80/32.P
10	100	42	FE3R.10-100/42.P
12	80	32	FE3R.12-80/32.P
12	100	42	FE3R.12-100/42.P
12	100	52	FE3R.12-100/52.P
14	100	42	FE3R.14-100/42.P
14	100	52	FE3R.14-100/52.P
16	100	42	FE3R.16-100/42.P
16	100	52	FE3R.16-100/52.P
16	120	72	FE3R.16-120/72.P
18	100	52	FE3R.18-100/52.P
18	120	72	FE3R.18-120/72.P
18	150	102	FE3R.18-150/102.P
20	100	52	FE3R.20-100/52.P
20	120	72	FE3R.20-120/72.P
20	150	102	FE3R.20-150/102.P
25	150	102	FE3R.25-150/102.P