


PUNTE COMPONENTI PER FORI PASSANTI IN HW


HW Through bore drill bits

HW Durchgangslochbohrer


HW Broca para agujero pasante



$\varnothing D$	L	DX - RH	SX - LH
5	70	FP.SB.I.70/5.D	FP.SB.I.70/5.S
6	70	FP.SB.I.70/6.D	FP.SB.I.70/6.S
6,35-I	70	FP.SB.I.70/635.D	FP.SB.I.70/635.S
7	70	FP.SB.I.70/7.D	FP.SB.I.70/7.S
8	70	FP.SB.I.70/8.D	FP.SB.I.70/8.S
9	70	FP.SB.I.70/9.D	FP.SB.I.70/9.S
10	70	FP.SB.I.70/10.D	FP.SB.I.70/10.S
11	70	FP.SB.I.70/11.D	FP.SB.I.70/11.S
12	70	FP.SB.I.70/12.D	FP.SB.I.70/12.S

PUNTE COMPONENTIBILI PER FORI PASSANTI IN HW
HW Through bore drill bits
HW Durchgangslochbohrer
HW Broca para agujero pasante


Ø D	L	DX - RH	SX - LH
4	58	FP.SB.G.58/4.D	FP.SB.G.58/4.S
5	58	FP.SB.G.58/5.D	FP.SB.G.58/5.S
6	58	FP.SB.G.58/6.D	FP.SB.G.58/6.S
6,35-I	58	FP.SB.G.58/635.D	FP.SB.G.58/635.S
7	58	FP.SB.G.58/7.D	FP.SB.G.58/7.S
8	58	FP.SB.G.58/8.D	FP.SB.G.58/8.S
9	58	FP.SB.G.58/9.D	FP.SB.G.58/9.S
10	58	FP.SB.G.58/10.D	FP.SB.G.58/10.S
12	58	FP.SB.G.58/12.D	FP.SB.G.58/12.S



Ø D	L	DX - RH	SX - LH
4	70	FP.SB.G.70/4.D	FP.SB.G.70/4.S
5	70	FP.SB.G.70/5.D	FP.SB.G.70/5.S
5.5	70	FP.SB.G.70/55.D	FP.SB.G.70/55.S
6	70	FP.SB.G.70/6.D	FP.SB.G.70/6.S
6,35-I	70	FP.SB.G.70/635.D	FP.SB.G.70/635.S
7	70	FP.SB.G.70/7.D	FP.SB.G.70/7.S
8	70	FP.SB.G.70/8.D	FP.SB.G.70/8.S
9	70	FP.SB.G.70/9.D	FP.SB.G.70/9.S
9.5	70	FP.SB.G.70/95.D	FP.SB.G.70/95.S
10	70	FP.SB.G.70/10.D	FP.SB.G.70/10.S
11	70	FP.SB.G.70/11.D	FP.SB.G.70/11.S
12	70	FP.SB.G.70/12.D	FP.SB.G.70/12.S